

RECEIVED

FEB 08 2002

DIVISION OF
OIL, GAS AND MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

I. General Information

1. Report Time Period: From (mo./yr.) 01/2001 Through (mo./yr.) 12/2001
2. DOGM File Number (Mine No): M/029/001
3. Mine Name: Devil's Slide Quarry
4. Mineral(s) Mined (or permitted to mine): Limestone
5. Type of mine XX Surface Mine or Underground Mine
6. Legal Description (Location of Lands Affected):
 1/4, 1/4, 1/4, Section 19, Township 4N, Range 4E
 1/4, 1/4, 1/4, Section 24, Township 4N, Range 4E
 1/4, 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Holcim, (U.S. Inc.)
8. Permanent Street Address: Aux. Rt. #3
City, State, Zip: Morgan UT 84050
Phone: 801 829 6821 Fax: 801 829 2100
9. Company Representative (or designated operator):
Name: Chester Goodson
Title: Plant Manager
Business Address: Aux. Rt. #3
City, State, Zip: Morgan UT 84050
Phone: 801 829 6821 Fax: 801 829 2100

 Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes XX No
2. If no - what was the last year of activity?
3. If yes - how much ore or mineral was mined? 748,899 tons limestone
34,129 tons sandstone
Tonnage figures are **metric tons** 783,028 tons total

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Limestone was mined from existing benches. No new surface disturbance was caused due to mining.

5. How much additional acreage was disturbed during the past year? None
6. How much acreage was reclaimed during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
Test seeding plot on PCM dump was evaluated during 2001. Results were good with some cover being produced. Will continue to monitor and evaluate during 2002.
8. What is the total disturbed acreage of entire project at year's end? 79 Acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining is planned with similar tonnage requirements to 2001. Permit will be reviewed and revised in 2002. New surface maps will be supplied.

NOTE: Section III., "Additional Information" applies only to **large mining operations.**

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Chester Goodson

Title of Operator: Plant Manager

Signature of Operator: 

Date: 04 February 2002

ib a:\forms\MR-AR

RECEIVED

FEB 08 2002

DIVISION OF
OIL, GAS AND MINING



Holcim (US) Inc.
6055 E. Croydon Road
Morgan, UT 84050

Phone 801 829 6821
Fax 801 829 2100
www.holcim.com/us

✓m/29/001
m/45/012

February 4, 2002

D. Wayne Hedburg, Permit Supervisor
Department of Natural Resources
Division of Oil, Gas and Mining
PO Box 145801
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801

Dear Mr. Hedburg:

Please find attached the annual reports for the Devil's Slide Quarry (M290001) and Poverty Point Quarry (M450012) for the year 2001.

The reclamation permit for Devil's Slide is currently under revision as you are aware and the total permit will be revised during the year 2002. There has been no activity at Poverty Point and none is planned for 2002.

If you desire any further information, please contact us at the Devil's Slide Plant.

Sincerely,



Chester Goodson
Chester.goodson@holcim.com

Plant Manager

CG/ksg

CC: Roy Stienmier, Ken George

RECEIVED

FEB 08 2002

DIVISION OF
OIL, GAS AND MINING